

Docket No.: 050203-0150

**PATENT**

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

In re Application of : Customer Number: 31824  
Mitsuhiko Nishina, et al. : Confirmation Number: 3412  
Application No.: 10/577,222 : Group Art Unit: 3748  
Filed: November 28, 2006 : Examiner: Binh Q. Tran  
Patent No. 7,467,512 :  
Issued: December 23, 2008 :  
For: EXHAUST GAS PURIFYING APPARATUS :  
AND EXHAUST GAS PURIFYING :  
METHOD OF AN ENGINE :

Commissioner for Patents  
Office of Patent Publication  
ATTN: Certificate of Correction Branch  
P.O. Box 1450  
Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322**

Sir:

In reviewing the above-identified patent, printing errors were discovered therein requiring correction in order to conform the Official Record in the application.

The errors noted are set forth on the attached copy of form PTO/SB/44 in the manner required by the Commissioner's Notice.

The changes requested herein occurred as a result of printing the Letters Patent and the Certificate should be issued without expense under Rule 322 of the Rules of Practice. Accordingly, Applicants request issuance of the Certificate of Correction.

U.S. Patent No. 7,467,512

Please charge any shortage in fees due in connection with the filing of this paper to Deposit Account 502203 and please credit any excess fees to such deposit account.

Respectfully submitted,

McDERMOTT WILL & EMERY LLP



Andrew D. Mickelsen  
Registration No. 50,957

18191 Von Karman Ave., Suite 500  
Irvine, CA 92612-7108  
Phone: 949.851.0633 ADM:wrj  
Facsimile: 949.851.9348  
**Date: February 10, 2009**

**Please recognize our Customer No. 31824  
as our correspondence address.**

ORC 455798-1.050203.0150

**UNITED STATES PATENT AND TRADEMARK OFFICE**  
**CERTIFICATE OF CORRECTION**

PATENT NO : 7,467,512

Page 1 of 1

APPLICATION NO. : 10/577,222

ISSUE DATE : December 23, 2008

INVENTOR(S) : Mitsuhiro NISHINA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**IN THE SPECIFICATION:**

Column 4, Line 63: Replace “NO+NO<sub>2</sub>+2NH<sub>3</sub>→2N<sub>2</sub>+3H<sub>2</sub>O” with --NO+NO<sub>2</sub>+2NH<sub>3</sub>→2N<sub>2</sub>+3H<sub>2</sub>O--

Column 4, Line 65: Replace “4NH<sub>3</sub>+3O<sub>2</sub>→2N<sub>2</sub>+6H<sub>2</sub>O” with --4NH<sub>3</sub>+3O<sub>2</sub>→2N<sub>2</sub>+6H<sub>2</sub>O--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

18191 Von Karman Ave., Suite 500  
Irvine, CA 92612-7108

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. **SEND TO: ATTENTION Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**